

## **TEST REPORT**

No.: SHIN2102008692ML

Date: Feb 10, 2021

Page: 1 of 3

CUSTOMER NAME: YIWU PRIOR OUTDOOR PRODUCT CO., LTD.

ADDRESS: #3508, BUILDING A, WANDA PLAZA, CHOUJIANG STREET, YIWU

CITY, ZHEJIANG PROVINCE, CHINA 322000

Sample Name : AERIAL FABRIC

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

\*\*\*\*\*

Test Required : Tensile Test

Date of Receipt : Feb 05, 2021

Testing Start Date : Feb 05, 2021

Testing End Date : Feb 10, 2021

Test result(s) For further details, please refer to the following page(s)

(Unless otherwise stated the results shown in this test report refer only to

the sample(s) tested)

Signed for SGS-CSTC Standards Technical Service (Shanghai)Co., Ltd.

cont Xu

Kant Xu

Authorized signatory





## **TEST REPORT**

No.: SHIN2102008692ML

Date: Feb 10, 2021

Page: 2 of 3

Tensile Test:

Test Method: Per client's requirement

Step 1. Fix the sample on the test equipment, please see the test photos;

Step 2. Drawing at the certain rate until the sample was broken;

Step 3. Check the location of fracture and record the force.

Test Result(s):

Sample	Broken force (kN)	Req. (kN)	Results	Location of fracture
1#	12.70	10	Pass	See photos

Note: The results comply with the client's requirement.

Testing Photos:







## **TEST REPORT**

No.: SHIN2102008692ML

Date: Feb 10, 2021

Page: 3 of 3







No.69, Block 1159, East Kang Qiao Road, Pudong District, Shanghai, China 201319 中国・上海・浦东康桥东路1159弄69号

邮编: 201319