

TEST REPORT

No.: SHIN2103012743ML

Date: Mar 09, 2021

Page: 1 of 3

YIWU PRIOR OUTDOOR PRODUCT CO., LTD. **CUSTOMER NAME:**

ADDRESS: #3508, BUILDING A, WANDA PLAZA, CHOUJIANG STREET, YIWU

CITY, ZHEJIANG PROVINCE, 322000, China

Sample Name **AERIAL NET**

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

Test Required : Tensile Test Date of Receipt Mar 04, 2021 Mar 04, 2021 **Testing Start Date Testing End Date** : Mar 09, 2021

Test result(s) For further details, please refer to the following page(s)

(Unless otherwise stated the results shown in this test report refer only to

the sample(s) tested)

Signed for SGS-CSTC Standards Technical Service (Shanghai)Co., Ltd.

Kelly Shi

Authorized signatory





TEST REPORT

No.: SHIN2103012743ML

Date: Mar 09, 2021

Page: 2 of 3

Maximum Breaking Load Test

Test Method: Per client's requirement

Step 1. Fix the sample on the test equipment, please see the test photos;


Step 2. Drawing at the certain rate until the sample was broken;

Step 3. Check the location of fracture and record the force.

Test Result(s):

Sample	Maximum Breaking Load (kN)	Location of fracture
-	9.70	See photos

Testing Photos:







TEST REPORT

No.: SHIN2103012743ML

Date: Mar 09, 2021

Page: 3 of 3





Before test

After test



****** End of report*****

